



July 2023





North America


 **United States 31 July 2023:** Rosenbauer America is recalling 13 units of 2020-2022 Commercial F-550, 2022 Commercial M2-106, M2-112, Commercial 567, 2021 Commander and Avenger vehicles equipped with certain Warn Industries VR EVO winches with a wireless handheld remote, because water may enter the handheld remote control for the winch and cause circuit board corrosion which can allow the winch to operate unintentionally - **injury risk**.

 **United States 31 July 2023:** Farber Specialty Vehicles is recalling one 2021 Ford Transit van equipped with a Cummins Onan QG 2800i generator because the fuel hose between the inline fuel filter and the Injection Pump Module


(IPM) may have inadequate clamp force, possibly resulting in a gasoline leak - **fire risk**.


 **United States 31 July 2023:** Kia America Inc. is recalling 121,411 units of 2017-2022 Niro and 2018-2022 Niro Plug-in Hybrid vehicles because fluid may leak into the printed circuit board inside the hydraulic clutch actuator which can result in an engine compartment fire - **injury risk**.


 **United States 31 July 2023:** Kia America Inc. is recalling 39,765 units of 2023 Soul, Sportage and 2023-2024 Seltos vehicles because the electronic controller for the Idle Stop & Go oil pump assembly may contain damaged electrical components that can cause the pump to overheat - **fire risk**.


 **United States 31 July 2023:** Tiffin Motorhomes Inc. is recalling 3 units of 2023


Phaeton motorhomes, equipped with Cummins L9 diesel engines, because the remote Stage 2 fuel filter hoses may have been damaged during production allowing the hoses to leak or disconnect - **crash/fire risk**.


 **United States 31 July 2023:** Autocar LLC is recalling 54 units of 2023 ACX (Xpeditor) vehicles, equipped with Cummins L9 diesel engines, because the remote Stage 2 fuel filter hoses may have been damaged during production allowing the hoses to leak or disconnect - **crash/fire risk**.

 **Canada 28 July 2023:** Lucid is recalling 57 units of 2022-223 Lucid Air vehicles because the nuts that attach the windshield wiper arms may loosen unexpectedly which could cause the wipers to slip and not clear the windshield properly - **crash risk**.


 **Canada 28 July 2023:** Airstream is recalling 3 units of 2023 Airstream Base Camp and Flying Cloud RV trailers because the wire connections for the SmartPlug 30 A shore power inlet could crack which could cause the connections to overheat or detach and cause a short circuit - **fire risk**.


 **United States 28 July 2023:** Temp-Air, a division of Sunbelt Rentals, is recalling 16 units of 2020-2022 EBB-60 trailers because the trailer tongues may deform and bend during use - **crash risk**.


 **United States 28 July 2023:** Midway Specialty Vehicles is recalling 4 units of 2022 Ford Transit vans equipped with certain Cummins Onan generators because the fuel hose between the inline fuel filter and the Injection Pump Module (IPM) may have inadequate clamp force, possibly resulting in a gasoline leak - **fire risk**.


 **United States 28 July 2023:** Chinook Motor Coach LLC is recalling 33 units of 2020-2024 Bayside motorhomes, equipped with certain Cummins Onan QG 2800i and Onan QG 2800i EVAP generator sets, because the fuel hose


between the inline fuel filter and the Injection Pump Module (IPM) may have inadequate clamp force, possibly resulting in a gasoline leak - **fire risk**.


 **United States 27 July 2023:** Lucid USA Inc. is recalling 778 units of 2022-2023 Air vehicles because software versions 2.0.64 and older may not respond properly to an inverter power module failure which can result in a loss of drive power without warning - **crash risk**.

 **United States 27 July 2023:** Lucid USA Inc. is recalling 5,523 units of 2022-2023 Air vehicles because the wiper arm nuts may loosen, causing the windshield wipers to fail - **crash risk**.


 **United States 27 July 2023:** Lucid USA Inc. is recalling 59 units of 2022-2023 Air vehicles with a software version between 2.015 and 2.0.50 because the rearview camera image may fail to display - **injury/crash risk**.


 **United States 27 July 2023:** Airstream Inc. is recalling 19 units of 2019-2023 Ford Transit, 2020 RAM and 2020-2022 Sprinter recreational vehicles upfitted by Creative Mobile Interiors because the fuel hose between the inline fuel filter and the injection pump module (IMP) may have inadequate clamp force, possibly resulting in a gasoline leak - **fire risk**.


 **United States 27 July 2023:** Porsche Cars North America Inc. is recalling 2,934 units of 2024 Cayenne, Cayenne S, Cayenne Coupe, Cayenne Turbo GT and Cayenne S Coupe vehicles because after the vehicle is turned off, the rear hazard warning lights and the parking lights may not illuminate if they are activated within 10 seconds after the gateway control unit shuts off - **crash risk**.


 **United States 27 July 2023:** Airstream Inc. is recalling 74 units of 2023-2024 Bambi, Basecamp, Caravel, Flying Cloud, Globetrotter, International, and Interstate travel trailers because the SmartPlug 30 Amp inlet manufactured with the


manganese bronze D-rings may crack or fail when over tightened - **fire risk**.


 **United States 27 July 2023:** General Motors LLC is recalling 767 units of 2013 Buick Verano, Chevrolet Camaro, Sonic and Volt vehicles because the driver-side air bag inflator may explode during deployment due to a manufacturing defect - **injury/death risk**.


 **United States 27 July 2023:** Honda is recalling 5 units of 2017, 2020 and 2022 CR-V vehicles because the certification label on the driver's side door states incorrect Gross Vehicle Weight Rating (GVWR), Gross Axle Weight Rating (GAWR) and tire size information - **crash risk**.


 **United States 27 July 2023:** Jaguar Land Rover North America LLC is recalling 668 units of 2021-2022 I-Pace vehicles because the high voltage coolant heater may fail to defrost the windshield - **crash risk**.


 **United States 27 July 2023:** Summit Bodyworks is recalling 12 units of 2019-2022 Ford Transit 350 vehicles equipped with certain Cummins Onan QG 2800i and Onan QG 2800i EVAP generator sets because the fuel hose between the fuel filter and Injection Pump Module (IPM) may not be properly secured which can cause a gas leak - **fire risk**.


 **United States 27 July 2023:** Altec Industries Inc. is recalling 535 units of 2022-2023 Aerial Devices (AT, TA, L44, L45, LR8, AA, AM, AN) and D series Digger Derricks (DH, DL, DM, DT) because the power inverter that converts electrical DC power to AC power may have been installed without a circuit breaker to protect the AC output circuit - **fire risk**.


 **Canada 27 July 2023:** Hyundai is recalling 11,120 units of 2023 Hyundai Elantra, Kona, Tucson and 2023-2024 Palisade vehicles because the circuit board for the transmission electric oil pump may be damaged - **fire risk**.


 **United States 26 July 2023:** Kawasaki Motors Corp. USA is recalling 991 units of 2023 ZX400SPFNL motorcycles because the alternator may fail due to a loose connection between the rotor and crank shaft causing an engine stall - **crash risk**.


 **United States 26 July 2023:** Sewn Products d.b.a. TigerTough is recalling 500 units of TigerTough seat covers because the stitching on the seat cover side flap may not break away as intended causing the side air bag to incorrectly deploy in the event of a crash - **injury risk**.


 **Canada 25 July 2023:** Ford is recalling 178,109 units of 2021-2023 Ford F-150 trucks because the rear axle wiring harness could rub against the rear axle housing and over time, this could cause damage to the wiring harness and the electric parking brake could apply suddenly while driving - **crash risk**.


 **United States 25 July 2023:** RevHD is recalling certain oil and PSI oil Hubcaps because the lens on the hubcaps may become loose causing lubricant to leak out of the wheel end - **crash risk**.


 **Canada 24 July 2023:** MicroBird is recalling 141 units of 2018-2024 Girardin G5 School Bus electric school buses built on a Ford chassis because a problem with the vehicle control software could cause overheating in the high-voltage battery pack and electrical arcing (sparks) in the charging circuit - **fire risk**.


 **Canada 24 July 2023:** Ford is recalling 6,571 units of 2023 Ford Escape, F-250 Super Duty, F-350 Super Duty, F-450 Super Duty and F-550 Super Duty vehicles because the instrument cluster could remain blank - **crash risk**.


 **Canada 24 July 2023:** Mack is recalling 3 units of 2023 Mack LR electric trucks because the fasteners that connect the high-voltage batteries to the busbar may have been over-tightened - **fire risk**.


 **Canada 24 July 2023:** Ford is recalling 201 units of 2023 Ford F-250, F-350, F-450 and F-550 vehicles because under certain conditions, the driver and/or passenger window automatic reversal system may not detect an obstruction when the window is closing - **injury risk**.


 **Canada 24 July 2023:** Volvo Trucks is recalling 8,084 units of 2022-2024 Volvo VAH, VHD, VNL and VNR trucks because the gears in the windshield wiper motor could wear - **crash risk**.


 **United States 24 July 2023:** Mack Trucks Inc. is recalling 19 units of 2024 LR garbage trucks because the reinforcing floor welds may be missing from around the passenger seat pedestal reducing floor strength - **injury risk**.


 **United States 24 July 2023:** Allison Transmission Inc. is recalling 584 units of Emergency Vehicle Series 6th Generation Transmission Control Modules (TCM) because the transmission control module (TCM) may fail to achieve the 4th gear transmission lockup needed to initiate the water pump - **injury risk**.


 **United States 24 July 2023:** Mack Trucks Inc. is recalling 9 units of 2022-2023 LR battery electric trucks because the rivnut threaded inserts inside the high-voltage battery may be over-tightened and break which could result in a short circuit - **fire risk**.


 **United States 24 July 2023:** Volvo Trucks North America is recalling 172 units of 2020-2024 VNR Electric vehicles because the rivnut threaded inserts inside the high-voltage battery may be over-tightened and break which could result in a short circuit - **fire risk**.


 **United States 24 July 2023:** Volvo Trucks North America is recalling 55,012 units of 2022-2024 VNR, VNL, VHD and VAH trucks because the windshield wiper motor gears may wear prematurely, causing the motor to fail - **crash risk**.


 **Canada 21 July 2023:** Forest River is recalling one 2023 Forest River Impression RV trailer because the safety stop for the outdoor griddle may not have been installed - **fire risk**.


 **United States 21 July 2023:** Ford Motor Company is recalling 5,558 units of 2023 F-53 recreational stripped chassis and F-59 commercial stripped chassis vehicles because corrosion in the Smart Data Link Connector (SDLC) may interfere with the Controller Area Network (CAN) communication, resulting in an inoperative instrument panel - **crash risk**.

 **United States 21 July 2023:** PACCAR Incorporated is recalling 72 units of 2023-2024 Peterbilt 536, 537, 548, 2023-2024 Kenworth T280, T480 and 2024 Kenworth T380 vehicles because the adhesive thread-lock may not have been applied to the four-flange mounted yoke bolt threads allowing the driveline fasteners to loosen - **crash risk**.


 **United States 21 July 2023:** Forest River Inc. is recalling 12 units of 2023 Impression fifth wheels vehicles because the exterior griddle may be stowed while still connected to LP gas line - **fire risk**.


 **United States 21 July 2023:** Ford Motor Company is recalling 1,339 units of 2023 Super Duty F250, F350, F450 and F550 vehicles because if the driver and front passenger door module experiences a low power condition and resets while the window is moving, the anti-pinch function may not detect an obstacle near the top edge and may not automatically reverse direction - **injury risk**.


 **United States 21 July 2023:** Ford Motor Company is recalling 112,225 units of 2014-2016 Transit Connect vehicles because the front door latch pawl may crack and prevent the door from latching - **injury risk**.


 **United States 21 July 2023:** Ford Motor Company is recalling 38,695 units of 2023


Escape, Super Duty F-250, Super Duty F-350, Super Duty F-450 and Super Duty F-550 vehicles, equipped with a digital instrument panel cluster, because the module may have been improperly soldered, preventing the instrument panel from illuminating - **crash risk**.


 **United States 21 July 2023:** Ford Motor Company is recalling 870,701 units of 2021-2023 F-150 vehicles equipped with a single exhaust system because contact with the rear axle housing may damage the wiring harness, causing the electric parking brake to activate unexpectedly - **crash risk**.

 **Canada 20 July 2023:** Fiat Chrysler Automobiles is recalling 55 units of 2023 Chrysler Pacifica plug-in hybrid (PHEV) models because a fuel line in the engine compartment may not have been made correctly - **fire risk**.


 **United States 20 July 2023:** Jaguar Land Rover North America LLC is recalling 3,134 units of 2019 Jaguar XE vehicles because due to wiring damage in the trunk, the rearview camera image may not appear on the display - **crash risk**.


 **United States 20 July 2023:** Chrysler is recalling 967 units of 2023 Pacifica Plug-In Hybrid Electric vehicles because the fuel line may be deformed, causing a fuel leak - **fire risk**.


 **Canada 19 July 2023:** Argo is recalling 1,798 units of 2020-2021 Argo Xplorer XR 500, 2021-2022 Xplorer XR 570, 2020-2021 Xplorer XRT 500 and 2021-2023 Xplorer XRT 570 ATVs because the check valve in the fuel vent hose may not have been installed correctly - **fire risk**.


 **United States 19 July 2023:** Sportsmobile Texas Inc. is recalling 13 units of 2021 Dodge Sportsmobile Pro Master and 2021-2022 Ford Sportsmobile Transit vans equipped with Cummins Onan QG 2800i or Onan QG 2800i EVAP generator sets because the fuel hose between the inline fuel filter and the Injection


Pump Module (IPM) may not be properly secured which can cause a gas leak - **fire risk**.


 **United States 19 July 2023:** Quality Vans is recalling 10 units of 2020-2023 Ford Transit vans equipped with Onan QG 2800i EVAP generators because the fuel hose between the inline fuel filter and the Injection Pump Module (IPM) may not be properly secured which can cause a gas leak - **fire risk**.


 **United States 19 July 2023:** Vanguard National Trailer Corporation is recalling 102 units of 2023-2024 trailer models built after November 2022 and equipped with a SAF Holland Tire Pilot Plus (TPP) tire inflation system, because the TPP electronic controller may open the check valves causing the tires to deflate - **crash risk**.


 **Canada 18 July 2023:** Polaris is recalling 3,428 units of Polaris 2022-2023 Indy, 2022-2024 RMK, 2022-2023 Switchback and 2022-2023 Voyager snowmobiles because the primary (drive) clutch could fail - **injury risk**.


 **Canada 18 July 2023:** Polaris is recalling 1,805 units of Polaris 2022 Indy, 2022-2023 RMK and 2022 Switchback snowmobiles because the starter ring gear could fail - **injury risk**.


 **Canada 18 July 2023:** Nissan is recalling 13,390 units of 2018-2023 Nissan Leaf because under certain conditions, the vehicle may not slow down after you release the accelerator pedal - **crash risk**.


 **United States 18 July 2023:** Cummins Inc. is recalling 1,135 units of L9 Diesel Engines because the remote Stage 2 fuel filter hoses may have been damaged during production allowing the hoses to leak or disconnect - **crash/fire risk**.


 **United States 18 July 2023:** Cummins Inc. is recalling 59 units of Model: B6.7 diesel engines because an insufficiently tightened bolt can cause the rear lifting bracket to detach from the cylinder head - **injury risk**.


 **United States 18 July 2023:** Titan Bus is recalling 69 units of 2017-2021 SRW and DRW school and multi-function school activity buses because the warning label may be missing from the Cross View Mirror - **crash risk**.


 **United States 18 July 2023:** Nissan North America Inc. is recalling 11,824 units of 2021 Versa and Kicks vehicles because an intermittent electrical connection in the electric power steering (EPS) torque sensor can disable the power steering assist - **crash risk**.


 **Canada 17 July 2023:** Grand Design RV is recalling 443 units of 2021-2024 Grand Design Momentum Fifth Wheel and Grand Design Solitude Fifth Wheel Trailer RV trailers because the U-bolts that attach the axles to the suspension may not be properly tightened - **crash risk**.


 **United States 17 July 2023:** Adaptive Mobility Systems Inc. is recalling 34 units of 2020-2023 Maxvan Pathway and 2021 Maxvan Route vehicles, equipped with certain Cummins Onan QG 2800i and Onan QG 28001 EVAP generator sets, because the fuel hose between the inline fuel filter and the Injection Pump Module (IPM) may have inadequate clamp force possibly resulting in a gasoline leak - **fire risk**.

 **United States 17 July 2023:** ST Engineering Hackney Inc. is recalling 59 units of 2022 Kidron refrigerated trailers equipped with Tire Pilot Plus tire pressure regulation systems (TPRS) because all 8 tires may experience a loss of tire pressure while driving faster than 45 mph - **crash risk**.


 **United States 17 July 2023:** Pleasure Way Industries Ltd is recalling 514 units 2021-2023 On Tour and Lexor motorhomes, equipped with certain Cummins Onan QG 2800i and Onan QG 2800i EVAP generator sets, because the fuel hose between the inline fuel filter and the injection pump module (IPM) may have inadequate clamp force possibly resulting in a gasoline leak - **fire risk**.


 **United States 17 July 2023:** Grand Design RV LLC is recalling 6,270 units of 2021-2024 Momentum and Solitude fifth wheels, equipped with certain CURT 7000 and 8000 lb axles, because the U-bolts may have been improperly tightened which can cause the axle to move out of position - **crash risk**.


 **United States 18 July 2023:** Nissan North America Inc. is recalling 66,159 units of 2018-2023 LEAF vehicles because the vehicle may accelerate unintentionally if the driving mode is changed ("D" to "B"; e-Pedal "On"; or "ECO" mode) after disengaging the cruise control - **crash risk**.

 **Canada 14 July 2023:** Tesla is recalling 3 units of 2023 Tesla Model S and Model X vehicles because the front-facing cameras may not have been aligned correctly - **crash risk**.


 **Canada 14 July 2023:** Tesla is recalling 645 units of 2021-2023 Tesla Model S and 2022-2023 Model X vehicles because the front seat belts may not have been reconnected to their anchors correctly during a repair - **injury risk**.


 **United States 14 July 2023:** Mazda North American Operations is recalling 227,335 units of 2014-2018 Mazda3 and 2016-2021 CX-3 vehicles because the rearview camera image may not display properly by showing a flickering or distorted image - **injury/crash risk**.


 **United States 14 July 2023:** Jayco Inc. is recalling 659 units of 2020-2021 Entegra Launch, Qwest, Jayco Melbourne and Melbourne Prestige motorhomes because the heating, ventilation and air conditioning (HVAC) blower motor circuit may be inadequate which can allow the wiring harness to overheat - **fire risk**.


 **United States 14 July 2023:** McLaren Automotive Incorporated is recalling 652 units of 2019-2020 600LT Coupe and Spider vehicles because the joint between the temperature sensor housing and the hose from the outboard radiator


may not be sealed properly which can result in coolant leaking into the engine compartment - **fire risk**.


 **United States 14 July 2023:** Tesla Inc. is recalling 1,337 units of 2023 Model S, Model X and Model Y vehicles because the forward-facing camera may be misaligned, causing some of the active safety features such as emergency braking, forward collision warning and lane assist to become unavailable without alerting the driver - **crash risk**.


 **United States 14 July 2023:** Tesla Inc. is recalling 15,869 units of 2021-2023 Model S and Model X vehicles because the front-row seat belts may not be connected properly to the pretensioner anchors which can cause the seat belts to detach - **injury risk**.


 **Canada 13 July 2023:** Roadtrek Inc. is recalling 47 units of 2021-2023 Roadtrek Chase, Play and Zion motorhomes because the cargo-carrying capacity may not have been calculated correctly - **crash risk**.


 **United States 13 July 2023:** Industrial Video & Control Co is recalling 4 units of 2021 MVT-900A MVT-3001-G surveillance trailers, equipped with certain Cummins Onan QG 2800i and Onan QG 2800i EVAP generator sets, because the fuel hose between the inline fuel filter and the Injection Pump Module (IPM) may have inadequate clamp force possibly resulting in a gasoline leak - **fire risk**.

 **Canada 12 July 2023:** Nova Bus is recalling 329 units of 2019-2023 Nova Bus LFS transit buses because the transmission yoke could separate from the transmission - **crash/injury risk**.


 **Canada 12 July 2023:** Toyota is recalling 4,252 units of 2023 Toyota Corolla, Corolla Cross, Highlander, Highlander Hybrid and Tacoma vehicles because the steering wheel spiral cable assembly could disconnect - **injury risk**.


 **Canada 12 July 2023:** BMW is recalling 43 units of 2023 BMW 7 Series and BMW i7 vehicles because the driver may not be able to control the windshield defrosting/defogging system and/or hazard lights using the interaction bar on the dashboard - **crash risk**.


 **Canada 12 July 2023:** Polestar is recalling 18 units of 2023 Polestar 2 vehicles because the left-front lower ball joint may not have been installed correctly in the steering knuckle - **crash risk**.

 **Canada 12 July 2023:** Prevost is recalling 60 units of 2023-2023 Prevost H3-45 Coach and 2023 H3-45 VIP buses because the right-front turn signal lamp could fail when the turn signal or hazard warning lights are turned on - **crash risk**.


 **United States 12 July 2023:** Nova Bus Inc. is recalling 334 units of 2019-2023 LFS transit buses because the transmission yoke may separate, resulting in driveshaft separation and a sudden loss of drive power - **injury risk**.


 **United States 12 July 2023:** Nova Bus Inc. is recalling 196 units of 2022-2023 LFS transit buses because during the hose manufacturing, the power steering hose may not have been assembled correctly which can result in hose fitting detachment and a loss of power steering assist - **crash risk**.


 **United States 12 July 2023:** Jayco Inc. is recalling 1,205 units of 2021-2022 Entegra Coach Accolade, Accolade XL, Jayco Seneca and Seneca Prestige recreational vehicles because the windshield wipers may fail resulting in reduced driver visibility - **crash risk**.


 **United States 12 July 2023:** BMW of North America LLC is recalling 384 units of 2023 740i, 760i xDrive and i7 xDrive60 vehicles equipped with an Interaction Bar because the Interaction Bar, located on the dashboard, may not activate the windshield defrosting/defogging system and/or the hazard warning lights. In addition, the


control buttons may not illuminate when pressed - **crash/injury risk**.

 **United States 12 July 2023:** Polestar Automotive USA Inc. is recalling 3 units of 2023 Polestar 2 vehicles because the front left lower ball joint may have been incorrectly installed, allowing the control arm to disconnect from the steering knuckle - **crash risk**.


 **United States 12 July 2023:** Toyota Motor Engineering & Manufacturing is recalling 43,442 units of 2021-2022 RAV4 Prime and 2022 Lexus NX450h+ plug-in hybrid electric (PHEV) vehicles because the electric current rectifying module contained within the DC-DC converter may have been damaged during production which can result in an electrical short-circuit - **fire risk**.


 **United States 12 July 2023:** Toyota Motor Engineering & Manufacturing is recalling 110,047 units of 2023 Corolla, Corolla Cross, Corolla Cross Hybrid, Highlander, Highlander Hybrid, Tacoma, 2023 Lexus RX350, RX350 Hybrid, RX500 Hybrid, 2023-2024 Lexus NX250, NX350 and NX350 Hybrid vehicles because an electrical connection inside the steering column's spiral cable assembly may be insufficiently welded, causing the connection to separate and deactivate the driver's air bag - **injury risk**.


 **United States 12 July 2023:** Toyota Motor Engineering & Manufacturing is recalling 110,047 units of 2023 Corolla, Corolla Cross, Corolla Cross Hybrid, Highlander, Highlander Hybrid, Tacoma, 2023 Lexus RX350, RX350 Hybrid, RX500 Hybrid, 2023-2024 Lexus NX250, NX350 and NX350 Hybrid vehicles because an electrical connection inside the steering column's spiral cable assembly may be insufficiently welded, causing the connection to separate and deactivate the driver's air bag - **injury risk**.


 **Canada 11 July 2023:** Textron is recalling 57 units of 2023 Cushman Hauler, Refresher, Shuttle and 2023 E-Z Go Express vehicles


because the wiring for the motor and speed sensor may not be secured properly - **crash risk**.


 **Canada 11 July 2023:** Prevost is recalling 31 units of 2023-2024 Prevost H3-45 Coach and 2023 H3-45 VIP buses because they were built with daytime running lamps (DRLs) that don't turn off when the fog lights are switched on - **crash risk**.


 **Canada 11 July 2023:** Bombardier Recreational Products is recalling 3,112 units of 2023 Lynx Shredder, Ski-Doo Freeride and Ski-Doo Summit snowmobiles because the exhaust gas temperature (EGT) sensor wiring harness could rub against the fuel return hose - **fire risk**.

 **United States 11 July 2023:** Prevost Car Inc. is recalling 50 units of 2021 and 2023 X3-45 Commuter buses because the bolt securing the passenger seat recline mechanism may loosen and disengage resulting in an unsecured seat back - **injury risk**.


 **United States 11 July 2023:** Prevost Car Inc. is recalling 93 units of 2023-2024 H3-45 and 2022-2024 H3-45 VIP vehicles because the right front turn signal light may fail when the turn signal or hazard warning lights are activated - **crash risk**.


 **United States 11 July 2023:** Seats Incorporated is recalling 8,853 units of Passenger Flip Seats because the passenger flip-up seat may be missing the safety clip that prevents the pivot rod from sliding - **injury risk**.


 **United States 11 July 2023:** Gulf States Toyota Inc. is recalling 195 units of 2023 Toyota RAV4 vehicles equipped with 17" black alloy accessory wheels because during installation of the alloy wheels, the tire valve stem may have been improperly installed or damaged. In addition, the load carrying capacity label may state the incorrect weight - **crash risk**.


 **Canada 10 July 2023:** BMW is recalling 191 units of 2023 BMW XM and 2024 BMW X5, X6 and X7 vehicles because the driver and/or front


passenger knee airbag(s) may not inflate properly in a crash - **injury risk**.


 **United States 10 July 2023:** BMW of North America LLC is recalling 1,981 units of 2024 X5 sDrive40i, X5 xDrive40i, X5 M60i, X5 M, xDrive 50e, 2024 X6 xDrive40i, X6 M60i, X6 M, 2024 X7 xDrive40i, X7 M60i, Alpina XB7 and 2023 XM vehicles because the knee air bag (driver and/or passenger) may not have been manufactured correctly which can result in the knee air bag not deploying as intended - **injury risk**.


 **United States 10 July 2023:** Boreas Campers is recalling 100 units of 2021-2022 XT travel trailers, equipped with certain SDS2 2-Burner Drop-in Cooktops, because the internal aluminium burner tubes that connect to the gas valves may fracture and cause a gas leak - **fire risk**.


 **United States 10 July 2023:** Dana Incorporated is recalling 2,247 units of Dana-Spicer Driveshafts because the driveshafts can break under certain loading conditions - **crash risk**.


 **United States 10 July 2023:** Yamaha Motor Corporation USA is recalling 211 units of 2022 Tenere 700 (XTZ7N) motorcycles because the front brake callipers may have been assembled with bolts that have an incorrect thread length which can damage the mounting hole threads in the brake calliper - **crash risk**.


 **Canada 07 July 2023:** Newmar is recalling 42 units of Newmar 2019-2023 Bay Star Class A Motorhome, 2020-2023 Bay Star Sport Class A Motorhome and 2022-2023 Super Star Class C Motorhome motorhomes because the seat belt anchor bracket for the dinette seats may not be strong enough - **injury risk**.


 **Canada 07 July 2023:** Toyota is recalling 94 units of 2023 Toyota Sequoia and Tundra vehicles because the chain on the spare tire carrier could break which could cause the spare tire to fall from the vehicle - **crash risk**.


 **United States 07 July 2023:** Toyota Motor Engineering & Manufacturing is recalling 1,398 units of 2023 Tundra, Tundra Hybrid, and Sequoia Hybrid vehicles because the steel chain used to secure the spare tire to the underside of the vehicle may have been insufficiently welded - **crash risk**.


 **United States 07 July 2023:** Ironman 4x4 USA II LLC is recalling 6,345 units of Pro Forge upper control arms because the upper control arm ball joint may experience premature wear and fail, causing a loss of steering - **crash risk**.

 **United States 07 July 2023:** Newmar Corporation is recalling 372 units of 2019-2023 Bay Star, 2020-2023 Bay Star Sport and 2022-2023 Super Star motorhomes because the seat belt brackets for the dinette seat belts were modified to avoid interference with the vehicle slide-out rollers in the floor - **injury risk**.


 **United States 06 July 2023:** Daimler Trucks North America LLC is recalling 82 units of 2023-2024 Freightliner eCascadia vehicles because the e-axle planetary gear set may not be welded properly which can cause the e-motor to detach from the final drive, resulting in an undetectable and sudden loss of drive power without the ability to restart the vehicle - **crash risk**.

 **United States 05 July 2023:** Lippert is recalling 13,997 units of Curt 7000 and 8000 lb axles because the U-bolts may have been improperly tightened which can cause the axle to move out of position - **crash risk**.

 **Canada 03 July 2023:** Polaris is recalling 471 units of 202-2023 Polaris Slingshot vehicles because a software problem could cause the rearview camera image to freeze when the transmission is shifted out of reverse - **crash risk**.

 **United States 03 July 2023:** Polaris Industries Inc. is recalling 22,218 units of 2020 Slingshot GT, 2021-2023 Slingshot S, Slingshot S Tech, 2020-2023 Slingshot R, Slingshot SL and

2022-2023 Slingshot SLR vehicles, updated with Ride Command Software, because after shifting out of reverse, the rearview camera image may freeze and display a blank screen if shifted into reverse again - **crash risk**.

 United States 03 July 2023: Mack Trucks Inc. is recalling 204 units of 2023-2024 LR garbage trucks because the wiper arm retention nuts may be loose and cause the windshield wipers to fail - **crash risk**.

Get in touch with one of our Product Recall Specialists for analysis on any of the above recall events.



US: +1 305 384 4825

APAC: +61 2807 30186

UK & EU: +44 20 3284 8844

This report (including any enclosures and attachments) has been prepared for the exclusive use and benefit of the addressee(s) and solely for the purpose for which it is provided. Unless we provide express prior written consent, no part of this report should be reproduced, distributed or communicated to any third party. Security Exchange Limited does not accept any liability if this report is used for an alternative purpose from which it is intended. The conclusions and recommendations contained herein are offered for the consideration of the addressee and are based on the information made available at the time of reporting. The addressee is under no obligation to adopt any of the recommended measures and Security Exchange limited cannot be held liable for any resulting errors or omissions.