




2023





North America


 **Canada 28 April 2023:** Brandt Industries Canada is recalling 29 units of 2022-2023 Brandt C550 and H450 trailers because the front amber side marker lamps don't meet the requirements of Canadian regulations - **crash risk**.


 **United States 28 April 2023:** Ford Motor Company is recalling 521 units of 2020-2022 Explorer Police Interceptor Utility vehicles, equipped with a 12.1-inch Integrated Computer Screen (ICS), because when the Display On/Off Button is used to turn the display to "Off" prior to placing the vehicle in reverse, the backup camera rear-view image will not appear on the display - **crash/injury risk**.


 **United States 28 April 2023:** Winnebago Industries Inc. is recalling 6,536 units of 2020-2023 Travato, 2021-2023 Solis and 2022-2023 Ekko motorhomes, equipped with certain Cummins Onan QG 2800i and Onan QG 2800i EVAP generator sets, because the fuel hose between the fuel filter and Injection Pump Module (IPM) may not be properly secured which can cause a gas leak - **fire risk**.


 **United States 27 April 2023:** Lordstown EV Corp is recalling 5 units of 2023 Endurance vehicles because the instrument cluster display screen may freeze on initial startup and not display critical safety information - **crash risk**.


 **United States 27 April 2023:** Fiat Chrysler Automobiles US LLC is recalling 165,503 units of 2019-2021 Ram ProMaster vehicles equipped with a 62TE transmission because the park pawl may not fully engage the park gear due to debris inside the transmission - **crash/injury risk**.

 **United States 27 April 2023:** Fiat Chrysler Automobiles US LLC is recalling 25,980 units of 2016-2017 Jeep Cherokee vehicles because the power transfer unit (PTU) may become damaged and disengage the transmission and differential, resulting in a loss of drive power or loss of park function - **crash/injury risk**.


 **United States 27 April 2023:** Fiat Chrysler Automobiles US LLC is recalling 2,564 units of 2022-2023 Jeep Wrangler Plug-In Hybrid Electric vehicles (PHEV) because the high voltage (HV) battery pack assembly was built with incorrect fasteners to secure the 200-amp fuse which can generate excessive heat - **crash risk**.


 **United States 27 April 2023:** Fiat Chrysler Automobiles US LLC is recalling 220 units of Mopar SVCE KIT- Hybrid Battery Packs because the high voltage (HV) battery pack assembly was built with incorrect fasteners to secure the 200-amp fuse which can generate excessive heat - **crash risk**.


 **Canada 27 April 2023:** Daimler Truck North America is recalling 5 units of 2023 Freightliner Business Class M2 short-wheelbase trucks because they were equipped with wheels and tires that may not be suitable for the vehicle which means they may not meet certain test requirements for electronic stability control (ESC) systems for heavy trucks - **crash risk**.


 **Canada 27 April 2023:** Fiat Chrysler Automobiles is recalling 429 units of 2022-2023 Jeep Wrangler 4xe plug-in hybrid electric vehicles (PHEV) because the wrong bolt may have been


used to connect the high-voltage battery fuse - **crash risk**.


 **United States 26 April 2023:** Tiffin Motorhomes Inc. is recalling 203 units of 2021-2022 Cahaba motorhomes because the spare tire carrier and molle rack may be incorrectly installed on the rear van doors which can cause them to detach while the vehicle is in transit - **crash risk**.

 **United States 26 April 2023:** Daimler Trucks North America LLC is recalling 3,452 units of short wheelbase 2020-2024 Freightliner Cascadia, Freightliner M2 Business Class, 2022 Western Star 4700 and 2020 Freightliner Classic Cascadia vehicles because they are equipped with an electronic stability control system and tire combination that may understeer during a J-turn - **crash risk**.


 **United States 26 April 2023:** BMW of North America LLC is recalling 5 units of 2023 X7 M60i and XM vehicles because the fasteners that connect the exhaust system and the catalytic converter may not have been tightened correctly - **fire risk**.


 **United States 26 April 2023:** BMW of North America LLC is recalling 31 units of 2022-2024 iX xDrive50 and 2023 i4 eDrive35, i4 eDrive40 and i4 M50 Hybrid Electric vehicles because the high voltage battery cell monitoring circuit may have improperly secured electrical connections which can result in an engine stall - **crash risk**.


 **United States 26 April 2023:** Hyundai Motor America is recalling 1,790 units of 2023 Genesis GV60 vehicles equipped with an all-wheel drive powertrain system because the rear driveshafts may fracture which can result in a loss of drive power - **crash risk**.


 **United States 26 April 2023:** Nissan North America Inc. is recalling 94,343 units of 2013-2017 LEAF vehicles because the Owner's Manual instructions for defroster operation are incorrect


and may result in reduced defroster performance under specific conditions - **crash risk**.


 **United States 26 April 2023:** Kia America Inc. is recalling 108,936 units of 2023 Sportage, Sportage Hybrid, Sportage Plug-in Hybrid, Niro Hybrid, Niro Plug-in Hybrid, Soul and Telluride vehicles, equipped with a digital instrument cluster containing a 4.2" LCD screen, because the instrument cluster may fail to display any information when the vehicle is started - **crash risk**.


 **Canada 26 April 2023:** Hyundai is recalling 357 units of 2023 Genesis GV60 vehicles because the rear axle shafts may not have been manufactured properly - **crash risk**.

 **Canada 26 April 2023:** Kia is recalling 7,090 units of 2023 Kia Niro, Soul, Sportage and Telluride vehicles because the instrument cluster screen could remain blank when the vehicle is started - **crash risk**.


 **Canada 26 April 2023:** BMW is recalling 2 units of 2023 BMW I7 and IX vehicles because the connectors for the high-voltage battery monitoring system may not be attached correctly - **crash risk**.


 **United States 25 April 2023:** Indian Motorcycle Company is recalling 4 units of 2022 Indian Chief Bobber, Indian Chief Dark Horse and Indian Chief Bobber Dark Horse motorcycles because they may be missing a belt guard reflector - **crash risk**.


 **United States 25 April 2023:** Subaru of America Inc. is recalling 4,030 units of 2023 Impreza vehicles because the brake light switch may be improperly adjusted and illuminate the brake lights without application of the brake pedal. The vehicle may also allow drivers to start and shift the transmission out of the PARK position without pressing the brake pedal - **crash risk**.


 **Canada 25 April 2023:** Subaru is recalling 364 units of 2023 Subaru Impreza vehicles


because the brake lamp switch may not have been adjusted correctly - **crash risk**.


 **Canada 25 April 2023:** Alliance RV is recalling one 2023 Alliance RV Valor trailer because the wrong wheels and tires, including the spare tire, were installed - **crash risk**.


 **Canada 24 April 2023:** Forest River is recalling 15 units of 2023 East To West Della Terra travel trailers because the cargo carrying capacity labels on certain trailers list the wrong unloaded vehicle weight (UVW) and cargo carrying capacity - **crash risk**.

 **United States 24 April 2023:** Forest River Inc. is recalling 64 units of 2023 East to West Della Terra & Silver Lake travel trailers because the Federal Placard may have been printed with incorrect dry weight and cargo carrying capacity - **crash risk**.


 **United States 24 April 2023:** Dana Incorporated is recalling 11 units of Spicer Ultimate Dana 60 Bracketless Crate Axles sold for Jeep Wrangler vehicles because the axel suspension bracket may prevent sufficient lubrication from reaching the pinion tail bearings - **crash risk**.


 **United States 24 April 2023:** Nova Bus Inc. is recalling 7 units of 2022-2023 LFS battery electric transit buses because the coolant line in the high voltage battery pack may not be fully seated and locked which can result in the loss of coolant and an electrical short circuit - **fire risk**.


 **United States 24 April 2023:** Forest River Inc. is recalling 37 units of 2023 Salem and Wildwood travel trailers because the brakes may be incorrectly wired which can result in a loss of brake function - **crash risk**.


 **United States 24 April 2023:** Forest River Inc. is recalling 137 units of 2022 Columbus CMF299RL fifth wheel vehicles because the riser


tube was not installed between the axle hangers, causing inadequate clearance for the tires - **crash risk**.


 **United States 24 April 2023:** Forest River Inc. is recalling 1,027 units of 2021-2023 Coachmen Galleria, Beyond, Forester, Sunseeker and 2021-2024 Nova motorhomes, equipped with certain Cummins Onan QG 2800i and Onan QG 2800i EVAP generator sets, because the fuel hose between the inline fuel filter and the Injection Pump Module (IPM) may have inadequate clamp force, possibly resulting in a gasoline leak - **fire risk**.


 **United States 21 April 2023:** Shred-Tech Corporation is recalling 14 units of 2021-2023 MDS-4-33 shredding trucks because shredded paper may accumulate in the space between the cutting knives and the bulkhead wall - **fire risk**.


 **United States 21 April 2023:** Thor Motor Coach is recalling 2,919 units of 2021-2023 Sequence, 2021-2024 Rize, Scope, Tellaro, 2023-2024 Dazzle and Twist motorhomes, equipped with certain Cummins Onan QG 2800i generator sets, because the fuel hose between the inline fuel filter and the injection pump module (IPM) may have inadequate clamp force, possibly resulting in a gasoline leak - **fire risk**.


 **Canada 21 April 2023:** Ford is recalling 327 units of 2023 Ford Bronco and Ranger vehicles because the wheel lug nuts may not have been properly tightened on the left-side of the vehicle - **crash risk**.


 **Canada 21 April 2023:** Forest River is recalling 208 units of 2021-2023 Coachmen Beyond, 2021-2022 Coachmen Nova, 2021-2022 Forest River Forester and 2022 Forest River Sunseeker motorhomes because a fuel hose on the generator may not be properly secured and could leak fuel - **fire risk**.


 **United States 20 April 2023:** Navistar Inc. is recalling 9,170 units of 2017-2023 International CV trucks because the brake pressure switch assembly may leak brake fluid into the brake pressure switch's electrical components and cause an electrical short-circuit - **fire risk**.


 **Canada 20 April 2023:** Micro Bird is recalling 7 units of 2018-2023 Micro Bird G5 Commercial Bus electric buses built on a Ford chassis because the AC charging harness could overheat while using a Level 2 charger - **fire risk**.


 **Canada 20 April 2023:** Triple E is recalling 84 units of 2020-2023 Leisure Travel Vans Wonder motorhomes because the bed stay brackets may have been installed upside-down - **injury risk**.


 **Canada 20 April 2023:** Navistar is recalling 1,201 units of 2017-2023 International CV trucks with hydraulic brakes because the brake pressure switch could leak - **fire risk**.


 **United States 20 April 2023:** Les Technologies Ecotuned Inc. is recalling 143 units of 2018-2023 E85 MK3 EV conversion systems because the charging harness may have a defective spliced connection in the AC power line - **fire risk**.

 **United States 19 April 2023:** Mack Trucks Inc. is recalling 4 units of 2022-2023 LR Battery Electric vehicles because the coolant line in the high voltage battery pack may not be fully seated and locked which can result in the loss of coolant and an electrical short circuit - **fire risk**.


 **United States 19 April 2023:** Triple E Recreational Vehicles is recalling 154 units of 2020-2023 Wonder W24RTB motorhomes because they may have an incorrectly installed bed stay bracket which can fail - **injury risk**.


 **United States 19 April 2023:** Heartland Recreational Vehicles LLC is recalling certain 2023 Big Country and Big Horn fifth wheels because the federal certification label may have incorrect tire information - **crash risk**.


 **United States 19 April 2023:** Maserati North America Inc. is recalling 56 units of 2022 MC20 vehicles because the brake lights may malfunction by unintentionally flickering due to faulty rear taillights - **crash risk**.

 **United States 19 April 2023:** Volvo Trucks North America is recalling 125 units of 2020-2024 VNR Electric vehicles because the coolant line in the high voltage battery pack may not be fully seated and locked which can result in the loss of coolant and an electrical short circuit - **fire risk**.


 **Canada 19 April 2023:** Heartland RV is recalling 8 units of 2023 Heartland Big Horn because the compliance label on certain RV trailers lists incorrect information - **crash risk**.


 **United States 18 April 2023:** Blue Bird Body Company is recalling 419 units of 2018-2021 All American and Vision School Buses, equipped with PowerDrive 7000 electric drive systems, because the System Control Module (SCM) may activate the anti-rollback feature, causing the vehicle to reverse faster than expected when the vehicle is in reverse and pointing downhill with the brake pedal not applied - **crash risk**.


 **United States 18 April 2023:** Mazda North American Operations is recalling 2,410 units of 2022-2023 CX-30 and 2023 CX-50 vehicles because the anti-lock brake system (ABS) Hydraulic Control Unit (HCU) may be damaged which can result in reduced braking ability - **crash risk**.


 **United States 18 April 2023:** Airstream Inc. is recalling 142 units of 2023 Rangeline motorhomes, equipped with certain Cummins


EVAP generator sets, because the fuel hose between the fuel filter and Injection Pump Module (IPM) may not be properly secured which can cause a gas leak - **fire risk**.


 **United States 18 April 2023:** Nova Bus Inc. is recalling 40 units of 2012-2019 LFS transit buses because the emergency exit window release and label may have been installed in the incorrect location and the emergency exit window opening may be insufficient - **injury risk**.


 **Canada 18 April 2023:** Nissan is recalling 433 units of 2023 Nissan Frontier because on certain trucks, the bead area of the tires may have been damaged when they were mounted onto the rims - **crash risk**.

 **Canada 18 April 2023:** Polaris is recalling 7,038 units of 2022-2023 Polaris RMK snowmobiles because the handlebar hooks may pose a puncture hazard and risk of serious injury if the rider's body impacts them in a crash - **injury risk**.


 **Canada 18 April 2023:** Mazda is recalling 156 units of 2023 Mazda CX-30 and CX-50 vehicles because damage inside the antilock brake system (ABS) hydraulic control unit (HCU) could cause an increase in brake pedal travel and reduced braking - **crash risk**.


 **Canada 18 April 2023:** Cummins is recalling 30 units of 2021-2023 Blue Bird Vision School Bus electric school buses because a software calibration error could cause the anti-rollback feature to activate - **crash risk**.


 **Canada 18 April 2023:** Airstream is recalling 28 units of 2023 Airstream Rangeline motorhomes because a fuel hose on the generator may not be properly secured and could leak fuel - **fire risk**.


 **Canada 17 April 2023:** Cummins is recalling 37 units of 2020-2023 Cummins Onan QG 2800I


EVAP generators because the fuel hose between the fuel filter and injection pump module may not be properly secured and could leak fuel - **fire risk**.


 **Canada 17 April 2023:** Winnebago is recalling 1,024 units of 2021-2023 Winnebago Micro Minnie RV trailers because the spare tire carrier could break and separate from the trailer - **crash risk**.


 **Canada 17 April 2023:** Cummins is recalling 185 units of 2021-2023 Pleasure-Way LEXOR motorhomes because a fuel hose on the generator may not be properly secured and could leak fuel - **fire risk**.

 **United States 17 April 2023:** 3M Transportation Safety Division is recalling 244 units of Flexible Prismatic Conspicuity Tape, Series 913-72 retroreflective sheeting, because the conspicuity tape may not be adequately reflective at certain angles - **crash risk**.


 **United States 17 April 2023:** Nissan North America Inc. is recalling 4,249 units of 2023 Titan and Frontier vehicles because the tires may have a tear in the inner bead which can cause a rapid loss of tire pressure - **crash risk**.


 **United States 17 April 2023:** Prevost Cars Inc. is recalling 280 units of 2021-2023 X3-45 Commuter buses because the foldable passenger seat cushion bolts may be loose and could fall out, allowing the seat cushion to detach from the seat frame - **crash risk**.

 **Canada 14 April 2023:** Nissan is recalling 455 units of 2023 Infiniti QX60 and 2023 Nissan Pathfinder vehicles because the driver's seat frame may not have been properly welded - **injury risk**.


 **United States 14 April 2023:** Winnebago Towable is recalling 10,492 units of 2021-2023 Micro Minnie travel trailers because the spare tire


carrier may fail when loaded with a certain off-road style tire - **crash risk**.


 **Canada 13 April 2023:** Michelin is recalling 77,606 units of 2017-2023 Michelin Agilis CrossClimate tires because they do not meet the minimum snow traction requirements of Canadian regulations - **crash risk**.


 **Canada 13 April 2023:** Fiat Chrysler Automobiles is recalling 4,082 units of 2021-2023 Jeep Gladiator, Wrangler and 2022-2023 Ram 1500 vehicles equipped with a 3.0 L diesel engine because the high-pressure fuel pump could fail - **crash risk**.


 **Canada 13 April 2023:** Forest River is recalling 451 units of 2023 Coachmen Apex, Brookstone, Chaparral, Chaparral Lite, Spirit, 2023 East To West Alta, 2022-2023 East To West Entrada and 2023 Prime Time MFG Crusader motorhomes and RV trailers because the fasteners that attach the solar panel may loosen or pull out - **crash risk**.


 **United States 13 April 2023:** General Motors LLC is recalling 40,428 units of 2019-2023 Chevrolet 4500HD, 5500HD and 6500HD Medium-Duty trucks because the brake pressure sensor assembly may leak brake fluid into the brake pressure switch and cause an electrical short-circuit - **fire risk**.


 **United States 13 April 2023:** Fiat Chrysler Automobiles US LLC is recalling 37 units of 2022 Ram 1500 vehicles because the B-pillar impact sensors may be missing which can result in delayed air bag deployment or non-deployment - **injury risk**.

 **United States 13 April 2023:** Fiat Chrysler Automobiles US LLC is recalling 45,711 units of 2021-2023 Jeep Wrangler, Gladiator and 2022-2023 Ram 1500 vehicles equipped with a 3.0L diesel engine because the high-pressure fuel pump (HPFP) may fail - **crash risk**.


 **United States 13 April 2023:** Fiat Chrysler Automobiles US LLC is recalling 8,459 units of Mopar High Pressure Fuel Pumps and 3.0L Diesel Engines because the high-pressure fuel pump (HPFP) may fail - **crash risk**.

 **United States 13 April 2023:** Fiat Chrysler Automobiles US LLC is recalling 131,700 units of 2021 Ram 1500 vehicles equipped with 5.7L eTorque engines because the powertrain control module software may cause an incorrect fuel mixture condition in the engine and result in an engine stall - **crash risk**.


 **United States 13 April 2023:** Michelin North America Inc. is recalling 542,110 units of Agilis CrossClimate C-Metric tires because they are labelled as snow tires but do not have sufficient traction to perform in all snow weather conditions - **crash risk**.


 **United States 13 April 2023:** Nissan North America Inc. is recalling 12,400 units of 2023 Rogue, Pathfinder and Infiniti QX60 vehicles because the driver's powered seat may not be fully secured to the seat frame, causing the seat frame welds to detach from the rear inboard seat bracket - **injury risk**.


 **United States 13 April 2023:** Forest River Inc. is recalling 2,616 units of 2021 Forester 2401BSD, FR3 F3A32DSF, Georgetown GTA36K7, 2022-2023 East to West Entrada, 2023 East to West Alta, Coachmen Apex, Brookstone, Chaparral and Chaparral Lite, Forest River Crusader, Sanibel, Shasta Phoenix, Coachmen Spirit and East to West Tandara vehicles because the solar panel mounting hardware may become loose and pull through the slot in the panel - **crash risk**.


 **United States 13 April 2023:** Field Van Inc. is recalling 20 units of 2019-2022 Sprinter vehicles, equipped with a Warn Winch and a wireless handheld remote, because water may enter the


handheld remote control for the winch and cause circuit board corrosion which can allow the winch to operate unintentionally - **injury risk**.


 **Canada 12 April 2023:** Ducati is recalling 82 units of 2023 Ducati Diavel motorcycles because the passenger foot pegs could break which could cause the passenger to suddenly lose foot support - **crash/injury risk**.


 **Canada 12 April 2023:** Honda is recalling 136 units of 2023 Honda CB300R and CMX300 motorcycles because the right-side engine crankcase cover could leak oil onto the exhaust pipe and/or the rear tire - **crash/fire risk**.

 **Canada 12 April 2023:** BMW is recalling 277 units of 2023 BMW X1 vehicles because a trim panel could interfere with the seat belts for the second-row outboard seats - **injury risk**.


 **United States 12 April 2023:** Honda is recalling 1,461 units of 2023 Rebel 300 (CMX300) motorcycles because the right engine crank house cover was incorrectly painted, allowing the press-fit plug to fall out - **injury/fire/crash risk**.


 **United States 12 April 2023:** BMW of North America LLC is recalling 1,465 units of 2023 X1 xDrive28i, X1 M35i vehicles because on the second-row outboard seats, the seat belts may have been pinched by an interior trim panel during vehicle assembly - **injury risk**.


 **United States 11 April 2023:** Meritor Inc. is recalling 65 units of front drive steer axles, models MFS and FF, because the front-drive steer axle fasteners may loosen, resulting in a complete separation of the axle assembly joints - **crash risk**.


 **United States 07 April 2023:** Volvo Trucks North America is recalling 236 units of 2020-2023 VNR Electric vehicles, equipped with Adaptive Cruise Control (ACC), because when the adaptive cruise control braking activates under light load


conditions, it can trigger an aggressive braking response - **crash risk**.


 **United States 07 April 2023:** Buell Motorcycles is recalling 30 units of 2021-2022 1190 RX and SX motorcycles because the index spring may be installed improperly - **crash risk**.


 **United States 07 April 2023:** Subaru of America Inc. is recalling 4,409 units of 2023 Ascent vehicles equipped with 20-inch wheels because the internal tire bead may have been damaged during the wheel mounting process - **crash risk**.

 **United States 07 April 2023:** Alamo Group Inc. is recalling 563 units of 2014-2019 Super Products Camel and Mud Dog vehicles because the tie rod could disconnect from the water tank strap, allowing the water tank strap to detach from the top of the vehicle - **crash risk**.


 **United States 07 April 2023:** Forest River Bus LLC is recalling 29 units of 2019-2022 Starcraft Prodigy school buses because the interior panels on the ceiling may be improperly secured - **injury risk**.


 **United States 07 April 2023:** Daimler Trucks North America LLC is recalling 48 units of 2023-2024 Thomas Built SAF-T-LINER C2, SAF-T-LINER Jouley, 2023 SAF-T-LINER EFX Chassis, HDX Chassis and SAF-T-LINER MVP-EF school buses because the tie rod may be missing a fastener, allowing the steer arm to detach - **crash risk**.


 **Canada 07 April 2023:** Subaru is recalling 201 units of 2023 Subaru Ascent vehicles because the tires may have been damaged when they were mounted onto the rims in the factory - **crash risk**.


 **Canada 07 April 2023:** Volvo is recalling 4 units of 2022-2023 Volvo VNR electric trucks because the regenerative braking system could


cause the rear wheels to lock up and skid during an adaptive cruise control (ACC) braking event - **crash risk**.


 **Canada 07 April 2023:** Daimler Truck North America is recalling one 2023 Thomas Built Saf-T-Liner C2 School Bus because the cotter pin may be missing from the tie rod castle nut on the front steer axle which could cause the tie rod to detach from the steering arm and cause a loss of steering control - **crash risk**.

 **Canada 06 April 2023:** General Motors is recalling 25,412 units of 2003-2023 Chevrolet Express and GMC Savana vehicles because an unused wiring harness for a rear HVAC blower motor, located in the left B-pillar area, could become damaged if exposed to moisture or contaminants - **fire risk**.


 **Canada 06 April 2023:** Land Rover is recalling 51 units of 2022-2023 Land Rover Range Rover vehicles because the latch for the seat frame on second-row left seat may not have been properly welded - **injury risk**.


 **Canada 06 April 2023:** BMW is recalling 26 units of 2023 BMW X5 vehicles because incorrect head restraint guide sleeves may have been installed on the second-row outboard seats - **injury risk**.


 **Canada 06 April 2023:** New Flyer is recalling 6 units of 2023 New Flyer XDE60 transit buses because the antilock brake system (ABS) could suddenly stop working due to a problem in the ABS control module event - **crash risk**.


 **United States 06 April 2023:** General Motors LLC is recalling 149,037 units of 2003-2023 Chevrolet Express Cutaway and GMC Savana Cutaway incomplete vehicles equipped with wiring for an optional rear heating, ventilation and air-conditioning (HVAC) system because when the HVAC blower motor circuit is left unused with


exposed connectors and wiring, the circuit can corrode and overheat - **fire risk**.


 **United States 06 April 2023:** BMW of North America LLC is recalling 235 units of 2023 X5 sDrive40i, X5 xDrive40i, X5 M50i, X5 M and X5 xDrive45e vehicles because the head restraints for the second-row outboard seats may have been improperly manufactured without locking tabs in the guide sleeves - **injury risk**.

 **United States 06 April 2023:** Navistar Inc. is recalling 44,887 units of 2016-2020 International DuraStar, WorkStar, 2017-2018 International TranStar, 2018 International ProStar, 2020 International HV, MV and 2018 IC Bus HC Commercial buses because the heating, ventilation, and air-conditioning (HVAC) blower motor circuit may have an insufficient wiring terminal that can overheat - **fire risk**.


 **United States 06 April 2023:** Ducati North America is recalling 293 units of 2023 Diavel V4 motorcycles because the right and/or left side passenger foot pegs may break while mounting or riding the motorcycle - **crash/injury risk**.


 **United States 06 April 2023:** Jaguar Land Rover North America LLC is recalling 500 units of 2022-2023 Land Rover Range Rover vehicles equipped with seven seats because the second-row seat frame may have been insufficiently welded - **injury risk**.

 **United States 06 April 2023:** Jaguar Land Rover North America LLC is recalling 5 units of 2023 Land Rover Range Rover Sport vehicles because they are equipped with incorrect rear taillights that do not illuminate correctly and the brake lights may not illuminate correctly - **crash risk**.


 **United States 06 April 2023:** Prevost Car Inc. is recalling 3 units of 2023 X3-45 and X3-45 VIP Entertainer motor coaches because the grommet that protects the electrical power distribution


cables passing through a metallic panel is insufficient, allowing the cables to chafe on the edges of the panel and potentially short circuit - **injury risk**.


 **United States 06 April 2023:** Nikola Corporation is recalling 364 units of 2022-2024 TRE BEV trucks because the electronic parking brake valve module (PVM) may fail to move into the park position when the parking brake is activated - **crash risk**.


 **Canada 05 April 2023:** Daimler Truck North America is recalling 49 units of 2022-2023 Freightliner 114SD, Business Class M2, Cascadia, Custom Chassis (FCCC) MT Chassis and 2022-2023 Western Star 4700, 47X, 4900 and 49X trucks because the cotter pin may be missing from the tie rod castle nut on the front steer axle which could cause the tie rod to detach from the steering arm and cause a loss of steering control - **crash risk**.


 **United States 05 April 2023:** Tesla Inc. is recalling 38 units of 2023 Model X vehicles, equipped with a full self-driving computer 4.0 and running software release version 2023.2.200, because weak camera signal strength may prevent the rear-view image from displaying - **crash/injury risk**.


 **United States 05 April 2023:** Maserati North America Inc. is recalling 11 units of 2023 MC20 Cielo vehicles because the windshield frame bonding may be insufficient and allow the frame to detach in a crash - **injury risk**.


 **United States 05 April 2023:** Porsche Cars North America Inc. is recalling 489 units of 2004-2005 Carrera GT vehicles because the spherical joints that connect the wishbone suspension components on the front and rear axles can fail due to damage from mechanical stress and corrosion - **crash risk**.


 **United States 05 April 2023:** Motor Coach Industries is recalling 140 units of 2019-2021 D45CRTLE, J3500 and J4500 coaches, equipped with a rear-mounted bike rack, because the rear lighting may be obstructed when bikes are installed on the bike rack - **crash risk**.

 **United States 05 April 2023:** New Flyer of America Inc. is recalling 30 units of 2023 XD60 and XDE60 60' articulated transit buses because the anti-lock brake system (ABS) module may lose power during hard braking, causing the ABS system to fail - **crash risk**.

 **Canada 04 April 2023:** Winnebago is recalling 57 units of 2021-2023 Winnebago Ekko motorhomes because the wiring for the house 12 V battery charging system may have been routed incorrectly and the electrical connections may be loose - **fire risk**.

 **United States 04 April 2023:** Nova Bus Inc. is recalling 10 units of 2022 LFS vehicles because the taillights may fail to illuminate when the headlights are activated - **crash risk**.

 **United States 04 April 2023:** Daimler Trucks North America LLC is recalling certain 2022 FCCC MT45G, S2C 106, 2022-2023 FCCC MT50E, MT55, S2RV Chassis, 2023 Freightliner 108 SD, 114 SD, Cascadia, M2 106, FCCC XCM Chassis, XCR Chassis, XCS Chassis, Thomas Built Bus SAF-T-LINER C2 and Western Star 4700, 47X, 4900, 49X commercial buses because the tie rod may be missing a fastener, allowing the steer arm to detach - **crash risk**.

 **United States 04 April 2023:** Cummins Inc. is recalling 15,622 units of Onan QG 2800i and Onan QG 2800i EVAP generator sets because the

fuel hose between the fuel filter and Injection Pump Module (IPM) may not be properly secured which can cause a gas leak - **fire risk**.

Get in touch with one of our Product Recall Specialists for analysis on any of the above recall events.



CONTACT

Get in touch for support from our global team of Auto Recall Specialists.



auto@securityexchange24.com



+44 (0)1491 683710



www.securityexchange24.com

EMERGENCY

To access emergency support in the event of an incident, call our 24/7 crisis centre.

US: +1 305 384 4825

APAC: +61 2807 30186

UK & EU: +44 20 3284 8844

Security Exchange provides a range of product contamination and recall, tamper and extortion mitigation and response consultancy services for the Contaminated Products Insurance market. In partnering with Salford University Business School, we deliver fully accredited, professional and bespoke industry-based training programmes in food and non-food, automotive, pharmaceutical, consumer goods and environmental management. For further information on these services, please go to www.securityexchange24.com or contact us at enquiries@securityexchange24.com.