




May 2023





North America


 Canada 31 May 2023: Volkswagen is recalling 659 units of 2022-2023 Audi E-Tron GT vehicles because the high-voltage electric heater could fail - **crash risk**.


 United States 31 May 2023: Bugatti is recalling one 2023 Chiron Super Sport vehicle because the incorrect wheels were installed on the vehicle - **crash risk**.


 United States 31 May 2023: Bentley Motors Inc. is recalling 1,008 units of 2022-2023 Bentayga 5-seat vehicles because the second-row seats may be installed incorrectly and not locked on all seat rails - **injury risk**.

 United States 31 May 2023: Iowa Mold Tooling Inc. is recalling 13 units of IMT Hydraulic Loaders because the stabilizer beams may have welds that crack over time and break under load - **injury risk**.


 United States 31 May 2023: Triple E Recreational Vehicles is recalling 210 units of 2023 Unity U24MB, U24cB, U24FX, U24MBL, U24RL, U24TB, and Wonder W24FTB, W24MBL, W24RL, W24RTB motorhomes because the 2-stage regulator may be improperly crimped which can cause a gas leak - **fire risk**.


 Canada 30 May 2023: Toyota is recalling 13,806 units of 2022-2023 Toyota Corolla Cross vehicles because a problem with the instrument panel could cause the passenger-front airbag not to open and inflate properly in a crash - **injury risk**.


 **United States 30 May 2023:** Chrysler is recalling 719 units of 2017-2020 Alfa Romeo Giulia and 2018-2020 Alfa Romeo Stelvio vehicles equipped with carbon ceramic matrix brakes because during certain driving manoeuvres, the brake system may exert an excessive clamp force that may fracture the rotor, decreasing the brake performance - **crash risk**.


 **United States 30 May 2023:** Tesla Inc. is recalling 137 units of 2022-2023 Model Y vehicles because the steering wheel fastener may be loose - **crash risk**.

 **United States 30 May 2023:** Toyota Motor Engineering & Manufacturing is recalling 96,007 units of 2022-2023 Corolla Cross vehicles because the instrument panel may have been produced without the required perforation which could result in the front-passenger air bag not deploying properly - **injury risk**.


 **United States 30 May 2023:** Wabash National Corporation is recalling 40 units of 2024 DVDBHPC and DVCVHPC dry van trailers because the king pin was not welded properly which can result in the king pin detaching within the upper coupler - **crash risk**.


 **Canada 29 May 2023:** Ford is recalling 27,152 units of 2020-2023 Ford Escape, 2022-2023 Ford Maverick and 2021-2023 Lincoln Corsair vehicles equipped with a 2.5 L HEV or PHEV engine because a manufacturing problem could lead to an engine failure - **fire risk**.


 **Canada 29 May 2023:** Ford is recalling 3,079 units of 2022-2023 Ford Bronco, 2023 Ford F-250 Super Duty and 2021-2022 Ford Ranger vehicles because the tire and loading information label lists the incorrect maximum weight of occupants and cargo - **crash risk**.


 **Canada 26 May 2023:** Nissan is recalling 10 units of 2023 Nissan Rogue vehicles because


the rear seat belt anchor bolts may not have been properly tightened - **injury risk**.


 **Canada 26 May 2023:** Keystone is recalling 60 units of 2021-2023 Keystone Arcadia RV trailers because the wardrobe slide-out could extend too far if the cabinet front detaches - **injury risk**.


 **Canada 26 May 2023:** Forest River is recalling 29 units of 2023 East to West Della Terra RV trailers because the furnace may have been installed incorrectly - **injury/fire risk**.


 **United States 26 May 2023:** Knapheide Manufacturing Company is recalling 38 units of 2022-2023 GM 2500HD, 2022 RAM 3500, Ford F-250, F-350, F-550 and 2023 GM 3500 vehicles equipped with certain Warn Industries VR EVO winches with a wireless handheld remote because water may enter the handheld remote control for the winch and cause circuit board corrosion which can allow the winch to operate unintentionally - **injury risk**.


 **United States 26 May 2023:** Ducati North America is recalling 3,315 units of 2020-2023 Panigale V2 motorcycles because the dashboard could automatically switch from low beam headlights to the headlight daylight position lamp (DRL) in automatic setting mode - **crash/injury risk**.


 **United States 26 May 2023:** Keystone RV Company is recalling 632 units of 2021-2023 Arcadia travel trailers because the backer board behind the cabinet for the wardrobe may not have been installed during production - **injury risk**.


 **United States 26 May 2023:** Forest River Inc. is recalling 258 units of 2023 East to West Della Terra and East to West Silver Lake travel trailers because the furnace may have been installed incorrectly, causing the cold air return to invert the cooktop flame and resulting in a gas leak inside the cabin - **fire risk**.


 **Canada 26 May 2023:** Navistar is recalling 402 units of 2022-2024 IC Bus CE School Bus, 2022-2024 IC Bus EV School Bus and 2021-2024 IC Bus RE School Bus because the warning light for the antilock brake system (ABS) does not remain on when there's a problem with the system and the vehicle is moving - **crash risk**.

 **Canada 26 May 2023:** Navistar is recalling 4,703 units of 2021-2024 IC Bus CE Commercial Bus, 2021-2024 International EMV, International HV, International HX, International Lonestar, International Lt, International MV and International RH vehicles because the warning light for the antilock brake system (ABS) doesn't stay on when there's a problem with the system, and the vehicle is moving - **crash risk**.


 **United States 26 May 2023:** Ford Motor Company is recalling 142,734 units of 2015-2019 Lincoln MKC vehicles because the battery monitor sensor may short-circuit and overheat causing a fire in the engine compartment while parked or driving - **injury risk**.


 **United States 26 May 2023:** Ford Motor Company is recalling 29,607 units of 2022-2023 Bronco, 2023 Super Duty F-250 and 2019-2023 Ranger vehicles because the Tire and Loading Information (TREAD) label states the incorrect load carrying capacity which can result in an overloaded vehicle - **crash risk**.


 **United States 26 May 2023:** Ford Motor Company is recalling 125,322 units of 2020-2023 Escape, 2022-2023 Maverick and 2021-2023 Corsair vehicles equipped with 2.5L HEV or PHEV engines because in the event of an engine failure, engine oil and fuel vapor may be released into the engine compartment and accumulate near ignition sources such as hot engine or exhaust components, possibly resulting in an engine compartment fire - **fire/injury risk**.


 **Canada 25 May 2023:** Jaguar is recalling 648 units of 2019-2024 Jaguar I-Pace vehicles


because there could be a problem inside the high-voltage battery which could create smoke or heat, melting or damaging the battery and nearby parts - **fire risk**.


 **United States 25 May 2023:** Jaguar Land Rover North America LLC is recalling 6,422 units of 2019-2024 Jaguar I-PACE vehicles because the high-voltage battery may overheat - **fire risk**.

 **United States 25 May 2023:** General Motors LLC is recalling 5 units of 2022 GMC Hummer EV and 2023 Cadillac Lyriq vehicles because certain connections within the high-voltage battery pack may be out of position or incorrectly welded which can cause a loss of drive power - **crash risk**.

 **United States 25 May 2023:** Marion Body Works Inc. is recalling 2 units of 2022 Gladiator and 2023 MetroStar emergency vehicles because after the vehicle is reversed, the transmission control module (TCM) may fail to achieve the 4th gear lockup needed to initiate the water pump - **injury risk**.


 **United States 25 May 2023:** Nissan North America Inc. is recalling 71 units of 2023 Nissan Rogue vehicles because the fastener in the rear seat belt anchor attachment points may not have been tightened properly and can loosen over time - **injury risk**.


 **United States 25 May 2023:** Autocar LLC is recalling 557 units of 2021-2023 Autocar Xpeditor (ACX) trucks because the right-side stand-up door latch may be assembled incorrectly - **crash risk**.


 **United States 25 May 2023:** Autocar LLC is recalling 373 units of 2020-2023 Autocar DC (Legend) trucks because the seat belt mounting fasteners may be improperly secured - **injury risk**.


 **United States 25 May 2023:** Navistar Inc. is recalling 72,817 units of 2021-2024 International HV, HX, LoneStar, LT, MV, eMV, and RH trucks, and IC Bus CE, 2021-2023 IC Bus RE and 2022-


2023 IC Bus TC Commercial Buses because the anti-lock brake system (ABS) indicator light does not remain illuminated when a malfunction exists and when the vehicle's ignition switch is on and the vehicle is in motion - **crash risk**.


 **United States 25 May 2023:** Navistar Inc. is recalling 19,376 units of 2021-2024 IC Bus RE, 2022-2024 IC Bus CE, and IC Bus EV school buses because the anti-lock brake system (ABS) indicator light does not remain illuminated when a malfunction exists and when the vehicle's ignition switch is on and the vehicle is in motion - **crash risk**.

 **United States 25 May 2023:** Fontaine Trailer Company is recalling 545 units of 2023-2024 Fontaine HACCFON51CTS 40-foot container trailers because the trailers may be missing the rear reflex reflectors - **crash risk**.


 **Canada 24 May 2023:** Shred-Tech is recalling 3 units of 2021-2023 Shred-Tech MDS-4-33 mobile shredding trucks because paper and materials could build up inside the shredder and overheat - **fire risk**.


 **Canada 24 May 2023:** Grand Design RV is recalling 28 units of 2023 Grand Design Transcend RV trailers because an emergency exit window may not have been installed - **injury risk**.

 **United States 24 May 2023:** Veoneer Brake Systems LLC is recalling 137,033 units of Brake Booster assemblies installed in certain Honda vehicles because the tie rod fastener that connects the brake booster and the brake master cylinder may have been improperly assembled during manufacturing which can cause the brake master cylinder to separate from the booster assembly - **crash risk**.


 **United States 24 May 2023:** Grand Design RV LLC is recalling 232 units of 2023 Transcend


travel trailers because these vehicles were manufactured without an emergency exit window in the main living area - **injury risk**.


 **United States 24 May 2023:** ST Engineering Hackney Inc. is recalling 120 units of 2021-2023 Kidron refrigerated trailers because the suspension pivot bolt may not have been properly tightened during the alignment process on certain Hendrickson suspensions with Quick-Align systems - **crash risk**.

 **United States 24 May 2023:** Winnebago Industries Inc. is recalling 1,328 units of 2020-2023 Winnebago Shell, 2021-2023 Winnebago Inspire, 2022-2023 Winnebago Vista, Adventurer, Forza, Journey and Itasca Sunstar motorhomes because the seat belt attachment may have been improperly tightened - **injury risk**.


 **Canada 23 May 2023:** Tiffin is recalling 7 units of 2021-2023 Tiffin Allegro Breeze motorhomes because when the condensation pan under the refrigerator is full, water can leak onto the electrical connections on the floor which could cause the connections to short circuit - **fire risk**.


 **Canada 23 May 2023:** Nissan is recalling 40 units of 2023 Nissan Leaf vehicles because the right-front brake line may have been damaged when it was made which could cause the brake line to corrode over time and create a brake fluid leak - **crash risk**.


 **Canada 22 May 2023:** REV Group is recalling 66 units of 2020-2024 Fleetwood RV Boulder, 2021 Fleetwood RV Southwind and 2022-2024 Holiday Rambler Vacationer motorhomes because the trailer hitch receiver could break and detach from the motorhome while towing a vehicle - **crash risk**.


 **United States 22 May 2023:** Nissan North America Inc. is recalling 758 units of 2023 LEAF vehicles because the right-hand brake tubes may have been damaged during production and could


corrode, possibly causing a hole in the brake line and a brake fluid leak - **crash risk**.


 **United States 22 May 2023:** Polestar Automotive USA Inc. is recalling 66 units of 2020-2021 Polestar 1 vehicles because defective high-voltage battery cells may cause the battery to overheat when fully charged - **fire risk**.


 **Canada 19 May 2023:** Ford is recalling 15,078 units of 2021-2023 Ford Bronco vehicles because there may not be enough space between the side of the seat and the interior trim to reach the latch plate for the front seat belt - **injury risk**.


 **United States 19 May 2023:** Mercedes-Benz USA LLC is recalling 7,558 units of 2022 EQS 450, EQS 580, 2023 Maybach S 580, Maybach S 680 and S 580e vehicles because the electronic stability program (ESP) software may malfunction which can result in disabled vehicle dynamics control systems, including the anti-lock brake system, acceleration slip regulation, electronic stability program and electronic brake force distribution (ABS, ASR, ESP, and EBD), as well as a vehicle speed display failure - **crash risk**.


 **United States 19 May 2023:** Forest River Inc. is recalling 6 units of 2023 Salem and Wildwood Travel Trailers because the brass fitting connected to the furnace pipe may have been manufactured without thread sealant - **fire risk**.


 **United States 19 May 2023:** SEA Electric LLC is recalling 84 units of SEA Drive SD120A battery electric drivetrain conversion kits for Hino model 195 vehicles because vibration may cause the traction motor mount to crack, destabilizing the traction motor - **crash risk**.


 **Canada 18 May 2023:** Fiat Chrysler Automobiles Canada is recalling 7,100 units of 2021-2023 Jeep Grand Cherokee vehicles because the intermediate steering shaft may not have been assembled correctly - **crash risk**.


 **United States 18 May 2023:** Terminal Investment Corporation is recalling 570 units of 2022-2023 Tico Spotter B 6.7 trucks equipped with certain Sheppard Steering Gears because the steering gear may have been assembled incorrectly which can cause the gear to fracture - **crash risk**.

 **United States 18 May 2023:** Ford Motor Company is recalling 175,550 units of 2021-2023 Bronco vehicles built with the 5-Door body style because the first-row seat belt latch plates may be difficult to access from their stowed position - **injury risk**.

 **United States 18 May 2023:** Altec Industries Inc. is recalling 5,143 units of 2021-2023 Aerial Devices, Digger Derricks, Service Bodies and Cranes because water can leak into the strobe lights which could cause an electrical short-circuit - **fire risk**.


 **United States 18 May 2023:** VinFast Auto LLC is recalling 999 units of 2023 VF8 vehicles because a software error may cause the multifunction head unit (MHU) display to go blank - **crash risk**.


 **United States 18 May 2023:** Navistar Inc. is recalling 4,030 units of 2001-2003 International 9100i, 2004-2009 International 9200i, 2009, 2011-2012, 2017 International ProStar and 2021 International RH vehicles because the back-up lights offer low visibility when the vehicle is in reverse and bobtail mode. Also, the vehicles have not been equipped with additional unobstructed back-up lights - **crash risk**.


 **United States 18 May 2023:** Gillig LLC is recalling 30 units of 2022 Low Floor CNG transit buses because an electrical failure may cause a short-circuit in the fuse box mounted underneath the driver's seat platform - **fire risk**.


 **United States 18 May 2023:** REV Recreation Group is recalling 1,186 units of 2020-2024


Fleetwood Bounder, Holiday Rambler Vacationer and 2020-2023 Fleetwood Southwind motorhomes because the tow hitch may become damaged due to stress or vehicle overloading which can cause the tow vehicle to separate from the motorhome - **crash risk**.


 **United States 18 May 2023:** Chrysler is recalling 89,372 units of 2022-2023 Jeep Grand Cherokee and 2021-2023 Jeep Grand Cherokee L vehicles because an incorrectly assembled steering column intermediate shaft may disconnect from the u-joint and result in a loss of steering control - **crash risk**.

 **Canada 17 May 2023:** Nova Bus is recalling 502 units of 2018-2023 Nova Bus LFS transit buses because the driver's seat back panel could interfere with the driver's seat belt - **injury risk**.


 **Canada 17 May 2023:** Mercedes-Benz is recalling 268 units of 2022-2023 Mercedes-Benz EQS Class and S Class vehicles because a software problem for the electronic stability control system (ESP) could cause the antilock brake system (ABS), acceleration slip regulation (ASR) and electronic brake force distribution (EBD) to malfunction - **crash risk**.


 **Canada 17 May 2023:** Lion Électrique is recalling 170 units of 2023 Lion C school buses because the driver's fixed front side window and fixed rear windows may not have been installed correctly - **injury/crash risk**.


 **United States 17 May 2023:** Nova Bus Inc. is recalling 166 units of 2012-2022 LFS vehicles because the driver's seat belt may not retract properly - **injury risk**.


 **United States 17 May 2023:** Foretravel Inc. is recalling 67 units of 2022-2024 Realm, Realm Presidential and FS450 motorhomes because the vehicle control module (ICM) may have a software error which can cause a loss of drive power or


disable other safety systems, such as the headlights or windshield wipers - **crash risk**.


 **United States 16 May 2023:** Porsche Cars North America Inc. is recalling 71 units of 2020-2022 Taycan vehicles because an incorrect warning indicator with an incorrect colour is displayed in the instrument cluster when notifying owners of worn brake pads - **crash risk**.


 **United States 16 May 2023:** Daimler Trucks North America LLC is recalling 47 units of 2023 Western Star 57X vehicles because the interior turn signals may flash too quickly and not align with the exterior turn signal flashing. Interior turn signals that consistently flash too quickly may not change their flash rate to alert the driver to replace the bulbs - **crash risk**.


 **United States 16 May 2023:** Dennis Eagle Inc. is recalling 286 units of 2020-2023 ProView vehicles because the driver's seat belt is too short and difficult to buckle, especially when the driver is wearing gloves - **injury risk**.


 **Canada 15 May 2023:** Ford is recalling 41,893 units of 2020-2023 Ford Explorer, 2020-2023 Lincoln Aviator and 2020-2022 Lincoln Corsair vehicles equipped with a 360-degree camera because a software problem could cause the rearview camera image not to appear on the SYNC display screen - **crash risk**.


 **Canada 15 May 2023:** Ferrari is recalling 34 units of 2022-2023 Ferrari 296 vehicles because the fuel tank connecting pipe could contact the high-voltage battery protection cover - **fire risk**.


 **United States 15 May 2023:** Mitsubishi Motors North America Inc. is recalling 89,907 units of 2022-2023 Outlander and 2023 Outlander PHEV vehicles because due to a software error in the in-vehicle infotainment system (A-IVI), the backup camera rearview image may not appear on the display - **crash/injury risk**.


 Canada 12 May 2023: Mitsubishi is recalling 17,364 units of 2022-2023 Mitsubishi Outlander and 2023 Mitsubishi Outlander PHEV vehicles because a software problem could cause the rearview camera image to not appear on the display screen - **crash risk**.

 Canada 12 May 2023: Mitsubishi is recalling 77 units of 2023 Mitsubishi Outlander PHEV vehicles because the bolts that attach the rear brake callipers may not have been tightened properly - **crash risk**.

 United States 12 May 2023: Ford Motor Company is recalling 422,201 units of 2020-2023 Explorer, Lincoln Aviator and 2020-2022 Lincoln Corsair vehicles equipped with a 360-degree camera because the video output may fail, preventing the rearview camera image from displaying - **crash risk**.


 United States 12 May 2023: Ford Motor Company is recalling 19 units of 2023 Super Duty F-250, F-350 and F-450 vehicles because the steering column upper shaft bolts may be missing or improperly tightened resulting in possible separation of the steering column from the adjoining components - **crash risk**.


 United States 12 May 2023: Fox Factory Inc. is recalling 1,578 units of 2021-2023 Jeep Wrangler, Gladiator, GM, RAM, 1500, 2500, Ford F-250, F-150 and F-350 vehicles equipped with Warn winches and wireless/handheld remotes because water may enter the handheld remote control for the winch and corrode the circuit board which can allow the winch to operate unintentionally - **injury risk**.


 United States 12 May 2023: Forest River Inc. is recalling 63 units of 2022-2023 Rockport work trucks because the trailer brake controller may have been incorrectly wired - **crash risk**.


 Canada 11 May 2023: General Motors is recalling 44,722 units of 2022-2023 Chevrolet


Equinox and 2020-2023 GMC Terrain vehicles because the coating on the connection bars for the lower universal anchorage system (UAS) may be too thick for securing a child or booster seat in the rear seat - **injury risk**.


 United States 11 May 2023: Altec Industries Inc. is recalling 44 units of 2021-2023 DT85 Digger Derricks because the Boom pressure limiter may allow the boom to lift loads above the rated capacity and over the Hydraulic Overload Protection (HOP) setting - **injury risk**.


 United States 11 May 2023: General Motors LLC is recalling 668,187 units of 2020-2023 Chevrolet Equinox and GMC Terrain vehicles because the four rear-seat lower child seat LATCH anchorage bars may have excessive powder coating which could prevent a child seat from being installed with the anchorage bars - **injury risk**.


 United States 11 May 2023: Chrysler is recalling 17,108 units of 2022-2023 Jeep Grand Cherokee L and Grand Cherokee vehicles because the air bag warning label may be missing from the dashboard - **injury risk**.


 United States 11 May 2023: Chrysler is recalling 132,099 units of 2014-2016 Jeep Cherokee vehicles equipped with a power liftgate because an electrical short in the power liftgate module may lead to a vehicle fire with the ignition on or off - **injury risk**.


 United States 11 May 2023: BMW of North America LLC is recalling 97,933 units of 2008-2014 MINI Clubman Cooper, Clubman Cooper S, Clubman John Cooper Works, and 2007-2013 MINI Hardtop 2-Door Cooper, Cooper S and John Cooper Works vehicles because the electronic control module in the driver's side footwell area may short-circuit due to corrosion from water and road salt - **fire risk**.


 **United States 11 May 2023:** Dennis Eagle Inc. is recalling 286 units of 2020-2023 ProView vehicles because the heating, ventilation and air-conditioning (HVAC) electrical circuit may overheat - **fire risk**.


 **United States 10 May 2023:** General Motors LLC is recalling 995,085 units of 2014-2017 Buick Enclave, Chevrolet Traverse and GMC Acadia vehicles because the driver's air bag inflator may explode during deployment due to a manufacturing defect - **injury/death risk**.


 **Canada 09 May 2023:** E-One is recalling 6 units of 2023 E-One Cyclone II and 2022-2023 E-One Typhoon fire trucks because certain sensors on the aerial device may not work properly - **injury risk**.


 **Canada 09 May 2023:** Daimler Truck North America is recalling 2,013 units of 2021-2024 Thomas Built SAF-T Liner C2 School Bus because the rear interior side body panels may not have been attached correctly - **injury risk**.


 **United States 09 May 2023:** Advance Stores Company Incorporated is recalling 1,546 units of Carquest Left and Right Lower Ball Joints because the ball joint may separate from the steering knuckle - **crash risk**.


 **United States 09 May 2023:** E-One Incorporated is recalling 24 units of 2022-2023 Cyclone N and Typhoon N vehicles because the electronic sensor for the aerial device may fail and not display accurate data on the angle of inclination - **injury risk**.


 **United States 09 May 2023:** Daimler Trucks North America LLC is recalling 23,590 units of 2021-2024 Thomas Built SAF-T-LINER C2 school buses because a rear interior joint may have been manufactured incorrectly resulting in insufficient joint strength - **injury risk**.


 **United States 09 May 2023:** Braun Ambulances is recalling 35 units of 2019-2023 Chief XL Type I, Express Plus Type I and Liberty Type I ambulances built on Chevrolet medium and heavy-duty chassis because the Liquid Spring suspension systems may come in direct contact with the right rear brake line, causing excessive wear and possibly resulting in the loss of the rear brakes - **crash risk**.

 **United States 08 May 2023:** Ferrari North America Inc. is recalling 425 units of 2022-2023 Ferrari 296 vehicles because the fuel tank connecting pipe may corrode due to unintended contact between the fuel tank connecting pipe and the high-voltage battery protection cover, potentially resulting in a fuel leak - **fire risk**.


 **United States 08 May 2023:** Triple E Recreational Vehicles is recalling 23 units of 2023 Unity U24MB, U24CB, U24FX, U24MBL, U24RL, U24TB and 2023 Wonder W24RL and W24RTB motorhomes because there may be exposed copper at the GFCI exterior receptacle which can cause an electrical short and arcing - **fire risk**.


 **United States 08 May 2023:** Daimler Trucks North America LLC is recalling 16 units of 2024 Thomas Built SAF-T-LINER C2 school buses because a rear exterior joint may have been manufactured incorrectly, resulting in insufficient joint strength - **injury risk**.


 **United States 05 May 2023:** Airstream Inc. is recalling 41 units of 2023 Atlas motorhomes because the 16-gauge branch wires may be under protected by a 20-amp fuse which could allow the wiring to overheat in the event of a short circuit - **fire risk**.


 **Canada 04 May 2023:** Jayco is recalling 9 units of 2023 Entegra Coach Emblem, 2024 Entegra Coach Vision XL, 2023 Jayco Alante Motorhome and Precept Motorhome because the


bolts that attach the rear brake callipers may not be properly tightened - **crash risk**.


 **Canada 04 May 2023:** Jayco is recalling 139 units of 2021-2023 Entegra Coach Ethos, 2023 Entegra Coach Expanse, 2023 Jayco Solstice and 2021-2023 Jayco Swift motorhomes because a fuel hose on the generator may not be properly secured and could leak fuel - **fire risk**.

 **Canada 04 May 2023:** Land Rover is recalling 832 units of 2022-2023 Land Rover Range Rover and 2023 Land Rover Range Rover Sport vehicles because the latch for the storage compartment in the second-row armrest could fail - **injury risk**.


 **Canada 04 May 2023:** Cummins is recalling 160 units of 2021-2023 Winnebago Ekko, Winnebago Solis and 2020-2023 Winnebago Travato motorhomes because a fuel hose on the generator may not be properly secured and could leak fuel - **fire risk**.


 **Canada 04 May 2023:** John Deere is recalling 59 units of 2023 John Deere Gator XUV590 and John Deere Gator XUV590 S4 vehicles because the fuel tank filler neck could leak under the fuel cap - **fire risk**.


 **United States 04 May 2023:** Jaguar Land Rover North America LLC is recalling 12,587 units of 2022-2023 Land Rover Range Rover and 2023 Land Rover Range Rover Sport vehicles because the second-row seat armrest storage compartment4 latch may fail, allowing the objects from within to be unsecured in the event of a crash - **injury risk**.


 **United States 04 May 2023:** Baby Trend Inc. is recalling 2,600 units of Hybrid 3-in-1 Combination Booster Seat-Desert Blue child seats because the latch assembly webbing that secures the child restraint system to the lower anchorages may fray which can reduce the strength of the


webbing and fail to properly restrain a child in a crash - **injury risk**.


 **United States 04 May 2023:** Ferrara Fire Apparatus Inc. is recalling 3 units of 2022 Ultra and Inferno fire trucks, equipped with a Warn Winch and a wireless handheld remote, because water may enter the handheld remote control for the winch and cause circuit board corrosion which can allow the winch to operate unintentionally - **injury risk**.


 **United States 04 May 2023:** Altec Industries Inc. is recalling 353 units of 2017-2022 DC, DB, DL, DM, DH, DT and D2/3/4000 Digger Derricks because the hardware that secures the removable auger hex extension bar to the drive unit coupler was not installed which may cause it to detach - **injury risk**.


 **United States 04 May 2023:** Jayco Inc. is recalling 11 units of 2022 Esteem, Odyssey, Redhawk and Greyhawk motorhomes built on Ford chassis because the paint along the weld seam of the fuel tank may peel and lead to corrosion of the exposed metal which can result in a fuel leak - **fire risk**.


 **United States 04 May 2023:** Outback Customs LLC is recalling 317 units of 2020-2022 4 Star, 2022 CM, Featherlite, Dodge RAM RCA, 2020-2023 Cimarron, Double D, Elite, Platinum horse trailers and 2021-2022 Mercedes Sprinter Vans equipped with certain SDS2 2-Burner Drop-in Cooktops because the internal aluminium burner tubes that connect to the gas valves may fracture and cause a gas leak - **fire risk**.


 **United States 04 May 2023:** Outback Customs LLC is recalling 7 units of 2018-2019 Cimarron and 2018-2020 Elite horse trailers equipped with certain 3 burner cooking stoves because the saddle valve securing bolt may be overtightened, possibly damaging the O-ring seal and causing a continuous gas leak - **fire risk**.


 **United States 04 May 2023:** Jayco Inc. is recalling 63 units of 2023-2024 Entegra Emblem, Vision, Vision XL, Jayco Alante, Precept and Precept Prestige motorhomes, built on Ford F-53 chassis, because the rear brake calliper attachment bolts may not be tightened correctly which can allow the calliper to loosen and possibly damage the wheel or brake lines - **crash risk**.

 **United States 04 May 2023:** Navistar Inc. is recalling 49 units of 2023 International MV trucks because the driveshaft tube seam weld may separate or tear resulting in drive line separation and a sudden loss of drive power - **crash risk**.


 **United States 04 May 2023:** Custom Fire Apparatus Inc. is recalling 2 units of 2023 MetroStar vehicles because after the fire truck is reversed, the transmission control module (TCM) may fail to achieve the 4th gear transmission lockup needed to initiate the water pump - **injury risk**.


 **United States 04 May 2023:** PJ Trailers is recalling 4,905 units of 2022-2024 LD, LY, LX, LS, CC, DD, TJ and TS trailers, equipped with a Demco EZ Latch Gooseneck Coupler because the coupler mounting bolts may loosen and cause the coupler to separate from the inner tube - **crash risk**.


 **United States 04 May 2023:** Jayco Inc. is recalling 1,124 units of 2021-2024 Ethos, Expanse, Solstice and Swift Class B recreational vehicles equipped with certain Cummins Onan QG 2800i and Onan QG 2800i EVAP generator sets because the fuel hose between the inline fuel filter and the Injection Pump Module (IPM) may have inadequate clamp force, possibly resulting in a gasoline leak - **fire risk**.


 **United States 04 May 2023:** Continental Automotive Systems Inc. is recalling 1,420 units of Electric Brake System (EBS) modules because the valves inside the Electric Brake System module may have been damaged during


manufacturing causing an internal brake module leak - **crash risk**.


 **Canada 03 May 2023:** Triple E is recalling 9 units of 2023 Leisure Travel Vans Unity and Leisure Travel Vans Wonder motorhomes because too much insulation may have been removed from a section of the power wires to the 120 V exterior power outlet - **fire risk**.


 **Canada 03 May 2023:** Bentley is recalling 94 units of 2021-2023 Bentley Flying Spur vehicles because the brackets that attach the rear entertainment screens to the front seatbacks may not have been installed correctly - **injury risk**.

 **United States 03 May 2023:** Bentley Motors Inc. is recalling 1,659 units of 2021-2023 Flying Spur vehicles because the rear entertainment screen retention bracket, located in the rear of the front seats, may have been incorrectly installed - **injury risk**.


 **United States 03 May 2023:** Winnebago Towable is recalling 4,313 units of 2022 Micro Minnie travel trailers because the solar panel mounting hardware may loosen which can cause the solar panel to detach from the vehicle - **crash risk**.


 **United States 03 May 2023:** Capacity of Texas is recalling 39 units of 2022 TJ Series 5000, 6500 and 9000 vehicles because the passenger side jump seat may be missing a safety clip that prevents the pivot rod from sliding - **injury risk**.


 **United States 03 May 2023:** Porsche Cars North America Inc. is recalling 3 units of 2020 911 Carrera S, 2021 Taycan Turbo and 2022 911 Carrera vehicles because due to a process error in the car body production line, various welds may be missing from the vehicle body - **injury risk**.


 **United States 03 May 2023:** Volkswagen Group of America Inc. is recalling 35,325 units of 2021-2022 ID.4 vehicles because the affected


vehicles may have been manufactured with door handles that allow water to enter the circuit board assembly which can cause the doors to open unexpectedly when the vehicle is subject to high lateral forces at speeds below 9 mph/15 kmh - **injury risk**.

 **United States 02 May 2023:** Mercedes-Benz USA LLC is recalling 3,823 units of 2023 EQE 350, S580e, 2022-2023 EQS 450, EQS 580, 2022 AMG EQS 53 and EQS 450+ vehicles because the high-voltage battery monitoring system software may not alert the driver of a battery malfunction - **injury risk**.

 **United States 02 May 2023:** Mack Trucks Inc. is recalling 5 units of 2024 LR electric garbage trucks equipped with electric horns because the circuit connecting the horn button to the horn is missing, making the horn inoperative - **crash risk**.

 **Canada 01 May 2023:** Thor Motor Coach is recalling 140 units of 2023-2024 Thor Motor Coach Dazzle, 2022-2023 Thor Motor Coach Rize, 2022-2024 Thor Motor Coach Scope, 2021-2022 Thor Motor Coach Sequence, 2021-2022 Thor Motor Coach Tellaro and 2023 Thor Motor Coach Twist motorhomes because a fuel hose on the generator may not be properly secured and could leak fuel - **fire risk**.

 **Canada 01 May 2023:** Yamaha is recalling 490 units of 2021 Yamaha Mountain Max and Yamaha Transporter snowmobiles because the snap ring that attaches the fuel dampener to the fuel rail could come loose and fall out - **fire risk**.

 **United States 01 May 2023:** Tiffin Motorhomes Inc. is recalling 231 units of 2020-2023 Breeze motorhomes because the condensation pan under the refrigerator may overflow and leak into the Molex electrical connections on the floor - **fire risk**.

Get in touch with one of our Product Recall Specialists for analysis on any of the above recall events.





Automotive Recall Summary



auto@securityexchange24.com



+44 (0)1491 683710



www.securityexchange24.com

EMERGENCY

To access emergency support in the event of an incident, call our 24/7 crisis centre.

US: +1 305 384 4825

APAC: +61 2807 30186

UK & EU: +44 20 3284 8844

Security Exchange provides a range of product contamination and recall, tamper and extortion mitigation and response consultancy services for the Contaminated Products Insurance market. In partnering with Salford University Business School, we deliver fully accredited, professional and bespoke industry-based training programmes in food and non-food, automotive, pharmaceutical, consumer goods and environmental management. For further information on these services, please go to www.securityexchange24.com or contact us at enquiries@securityexchange24.com.